Errors in the time displayed by DTV receivers

Eng. Laura Quesada Del Busto

laura@lacetel.cu



Introduction



E-mail to assistance DTV users tvdigital@lacetel.cu

- ❖ From November, 2015, DTV users began to complain that some of their receivers showed an hour late while receiving DTV broadcasted.
- ❖ The Service Provider informed the problem was in those specific receivers, given that not all DTV receivers showed this offset in time.
- ❖ In LACETEL's DTV Lab, we proposed to find the origin of the problem with a scientific methodology.



Problem

Why receivers show differences in time, if they receive same broadcasted transport stream?





Goal

❖ Identify the causes of differences in the time shown by DTV receivers, and find solutions to this problem.



Previous Knowledge

Where is date and time information located in Transport Stream?

❖ The Service Information defined in ETSI Standard EN 300 468 specifies that the date and time information is transmitted in the TDT (Time and Date Table) and TOT (Time Offset Table) tables.

Main Tasks

- Study the structure of TDT and TOT tables from that indicated in ETSI EN 300 468 standard.
- Analyze the content of TDT and TOT tables in the broadcasted transport stream.
- Check if receivers correctly update date and time information.

TDT- Time and Date Table

- ❖ Provides the current date and time in UTC zone.
- ❖ Packets with PID = 0x14 and table_id = 0x70.


TOT- Time Offset Table

- ❖ Provides the time offset relative to UTC applied to each time zones.
- ❖ Packets with PID = 0x14 and table_id = 0x73.



TOT- Time Offset Table

Transport Stream



TOT- Time Offset Table

Main fields in local_time_offset_descriptor:

local_time_offset_polarity: indicates if time is behind or ahead of UTC.

time_of_change: date and time when the time change takes place.

local_time_offset: offset time when it is early to time_of_change.

next_time_offset: offset time when it is equal to or after time_of_change.

Content of TDT and TOT tables in broadcasted transport stream

Test conditions:

- Analysis of a TS file recorded from broadcasted DTV on December 30, 2015, at 8:17 am.
- Software tools :
 - MPEG-2 TS Packet Analyzer 2.4.5.0
 - 4T2 Content Analyzer



Content of TDT and TOT tables in broadcasted transport stream

Test results:

- ▶ PID = 0x14, table_id = 0x70 TDT
- PID = 0x14, table_id = 0x73 **TOT**
- ✓ UTC_time = 2015/12/30, 13:17:15
- Country code: Cuba

- Polarity: negative
- Time_of_change: 2015/10/10 05:00
- Local_time_offset: 05:00
- X Next_time_offset: 06:00



Automatic update of date and time in DTV receivers

Receiver	Result
STB KONKA KSDT863-M	X
STB KONKA KHDT875-A	×
STB SOYEA SDP160	×
STB RUNCH DTT1513	
STB RUNCH DTT 1900	×
STB RealTV HMA1	×
STB GELECT SD-HL215	×

Receiver	Result
STB GELECT HD-HL1209	
STB MiCO DT46-N03	×
STB MiCO DT25-2080	• •
	X
STB HAIER HDMB-6000T	×
STB HAIER HDMB-2000T	X
iDTV ATEC 32L14D	\checkmark
IDTV KONKA KDL32KT627	X

Main achievements

- Services Provider was notified about the errors in the TOT table transmitted transport stream.
- Since 23 January 2016 the information transmitted is correct.
 - Time_of_change: 2016/04/10 05:00:00
 - Local_time_offset: 05:00
 - Next_time_offset: 04:00
- The automatic update of date and time in DTV receivers evaluation process of Digital TV receivers was optimized.



Main achievements

Manufacturers of receivers that failed were notified.

Receiver	Result
STB KONKA KSDT863-M	X
STB KONKA KHDT875-A	×
STB SOYEA SDP160	×
STB RUNCH DTT1513	
STB RUNCH DTT 1900	X
STB RealTV HMA1	×
STB GELECT SD-HL215	×

Receiver	Result
STB GELECT HD-HL1209	
STB MiCO DT46-N03	×
STB MiCO DT25-2080	×
STB HAIER HDMB-6000T	×
STB HAIER HDMB-2000T	×
iDTV ATEC 32L14D	1
IDTV KONKA KDL32KT627	×



Main achievements

Manufacturers of receivers that failed were notified.

Receiver	Result
STB KONKA KSDT863-M	
STB KONKA KHDT875-A	
STB SOYEA SDP160	×
STB RUNCH DTT1513	
STB RUNCH DTT 1900	
STB RealTV HMA1	
STB GELECT SD-HL215	×

Receiver	Result
STB GELECT HD-HL1209	
STB MiCO DT46-N03	
STB MiCO DT25-2080	
STB HAIER HDMB-6000T	×
STB HAIER HDMB-2000T	×
iDTV ATEC 32L14D	1
IDTV KONKA KDL32KT627	

Conclusions

- ❖ The causes of differences in the time shown by digital TV receivers were:
 - errors in the information contained in the TOT table
- some receivers did not update date and time information from TOT table

Recommendations

Update from server the information in local_time_offset, time_of_change and next_time_offset fields, before the occurrence of next time change.



DIGITAL TELEVISION LABORATORY





www.lacetel.cu